



## LuK Service Info



# Misalignment of diaphragm spring fingers

Manufacturers: PSA/Peugeot, Citroën

LuK RepSet: 623 3325 00  
623 3325 09  
623 3325 33  
601 0021 00



Fig. 1: Misalignment of diaphragm spring fingers on a dismantled clutch

The diaphragm spring fingers of the pressure plate in the LuK RepSet are misaligned in its uninstalled condition (Fig. 1). This design characteristic is safe and does not represent a component defect.

During the installation of the clutch, the diaphragm spring aligns itself to its working position. In so doing, the diaphragm spring fingers align themselves properly and provide for the fully reliable operation of the clutch.

### Note:

All components of every LuK RepSet undergo 100% inspection on the assembly line. They meet the technical specifications and are suitable for unrestricted use on the vehicles listed in the catalog.

Please observe the vehicle manufacturer specifications!

### You want more? We can help!

Phone: +44 (0) 1432 264 264  
Fax: +44 (0) 1432 375 760  
aftermarket.uk@schaeffler.com  
www.repxpert.co.uk

SCHAEFFLER  
REP>XPERT