

Technical *Info*

Replacement of Timing Belt Kit CT 946 K2 with Kit CT 1044 K1

Fig. 1
CT 946

Problem:

The belt supplied with CT 1044 K1 is different in terms of appearance and number identification from the CT 946 belt installed so far. **(Fig. 1)**



Cause:

The CT 1044 is reinforced with additional belt back fabric and can also be used for the older TDI engines. **(Fig. 2)**

Fig. 2
CT 1044 with belt back fabric

Solution:

Kit CT 946 K2 is no longer available and has been replaced by CT 1044 K1. The distinguishing engine number is thus omitted.

