



SERVICE-INFO

Replacing tensioner lever 534 0062 20 in 534 0340 10 for Mercedes Actros

Vehicle

manufacturer: Mercedes

Model: Actros

Engine models: OM

541.920, 541.921,
541.922, 541.923,
541.924, 541.925,
541.926, 541.927,
541.941, 541.943,
541.944, 541.947,
542.920, 542.921,
542.922, 542.925,
542.940, 542.960

OE-Nos.:

(1) A 541 200 2470 (old)
(2) A 541 200 2570 (new)

Item nos.:

(1) 534 0062 20 (old)
(2) 534 0340 10 (new)



Image 1: 534 0062 20 (replaced design)




Image 2: 534 0340 10 (current design)

Tensioner lever 534 0062 20 (image 1) is no longer available and has been replaced by item no. 534 0340 10 (image 2).

The fundamental differences between the two designs are a new deflecting pulley with improved running characteristics and a modified shield plate.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 11.2009

INA 0047

Technical subject to change

© 2009 Schaeffler Automotive Aftermarket oHG

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

