SI-260721
Service-Information Turbocharger

Turbocharger looks similar with the same flange dimensions must be checked to ensure they have the correct part number

Introduction:
As part of model changes and facelift introductions, the vehicle manufacturer has installed turbochargers with different types of electric actuators. Errors may appear in the manufacturers' spare parts lists because of mixed installations.

Note:
The turbochargers differ in the number of electrical pins on the actuator and the connector profile. Another distinguishing feature is the position of the nameplate. Use the nameplate to compare the model numbers and OE numbers.
Installing the wrong turbocharger or replacing the actuator will immediately void the warranty.

With regard to T914789 and T914796, please refer to Service Information SI-200928.

Instructions:
Before adding the initial fill additive or installing the turbocharger, compare the model number on the nameplate with the numbers on the old part.





Vehicle Manufacturer: BMW
Vehicle: 116d (F20, F21) ; 118d (F20, F21) ; 218d (F22, F87) ; 316d (F31, F80, E90, F91) ; 318d (F30, F31, F34, F80, F80) ; 418d (F36) ; X1 (E84) 16d ; X1 (E84) 18d
Engine code: N47 D20 C

Validity: This service information is valid for renewing the turbocharger with
BTS reference: T916513 **BTS-Service-Set-Nr:** T981598

OE-part.no.: 11657812321, 11658506722, 11658513122, 11658513123, 11658518204, 11658518205
Manufacturer part no.: 9VB01, V41VEGSR022B, V41VEG-SR022B

Please note: OE-references are only for means of comparison. The content of this Service Information is non-binding and is only for informational purposes. The manufacturer specifications have to be adhered to.

BTS GmbH
Paradeisstraße 56
D-82362 Weilheim

Verkauf - Tel.: +49 881 627 – 300
Fax: +49 881 627 – 311

Technik - Tel.: +49 881 627 – 302
Fax: +49 881 627 – 311

Mail: info@bts-turbo.de
Web: www.bts-turbo.de