



LuK Service Info



Part Nr: 631 0878 09 — 310/310mm XGW6

Manufacturer: LANDINI, MASSEY FERGUSON,
STEYR & VALTRA

Informations de volant-moteur/
Información del Volante-motor/
Informazioni volano


Art.-Nr.: **631 0878 09**

631 0878 09 replaces/ersetzt/
remplace/sustituye a/sostituisce Valeo


Info: Flywheel Information/
Schwungradinformation/





631 0878 09 = Repset only


 The location recess of 0.5mm depth and external register diameter of 362.114 – 362.290mm must be restored when flywheel is machined.

guide de 362.114 – 362.290 mm lorsque le volant-moteur est rectifié.

 Die der Bearbeitung des Schwungrads müssen die Einbautiefe von 0,5 mm und der externe Registerdurchmesser von 362.114–362.290 mm wiederhergestellt werden.

 Deben mantenerse la distancia relativa a la zona de fricción a 0,5 mm de profundidad y el diámetro de fricción externo a 362.114 – 362.290 mm cuando el volante esta mecanizado.

 Il faut restaurer l'épaulement de montage de 0,5 mm de profondeur et le diamètre de l'épaulement

 Riportare la cavità della sede ad una profondità di 0,5 mm e il diametro di centraggio esterno a 362.114 – 362.290 mm quando si rettifica il volano.



- For accurate model information please see LuK catalogue
- Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog
- Pour plus d'information sur les applications veuillez vous référer au catalogue LuK
- Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK
- Per informazioni sul modello consultare il catalogo LuK

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repexpert.co.uk

SCHAEFFLER
REP>XPERT