

Optimized tensioning pulley 531 0564 30

Manufacturer:

Seat, Volkswagen

Model:

- Seat Polo
- Volkswagen Cordoba, Ibiza

Engine:

1.4i 16V (AFH)

LuK AS Part No.: 531 0564 30

OE-No.:

036 109 243 J
036 109 243 G (replaced)
036 109 243 D (replaced)




Fig. 1: 531 0564 30 (front view)




Fig. 2: 531 0564 30 (side view)

Tensioning pulley **531 0564 30** (sinus pulley) is a noise-optimized tensioning pulley, developed specially for the applications outlined above.

The red markings (**fig. 1** and **fig. 2**, arrows) highlight the features.

The running surface of the tensioning pulley has diagonal elevations (**fig. 2**).

Note:

The unusually formed running surface is **not** a production fault!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or at www.RepXpert.com.

Issued 11.2007

INA 0009

Technical subject to change

© 2007 LuK-Aftermarket Service oHG

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 275 146

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

