



INA Service Info

INA Timing Chain Kit 559 0156 30

Changed chain width

Vehicle manufacturers: Audi, Seat, Škoda, VW

Models:

Audi: A1, A3
 Seat: Altea, Ibiza, Leon, Toledo
 Škoda: Rapid, Roomster 5J, Octavia III, Fabia
 VW: Golf VI, Polo 6R, Caddy III, Jetta IV, Beetle 5C, Touran

Engine: 1.2 TSI

Part no.: 559 0026 30 (narrow timing chain, no longer available)
 559 0156 30 (wide timing chain)



Figure 1: INA Timing Chain Kit 559 0156 30

See parts catalogue for current assignment

The timing chain for the 1.2 TSI engine was converted to a wider variant as used by O.E during the course of the 2011 model year. For this reason, the previous Timing Chain Kit (part no.: 559 0026 30) has been discontinued. This has been replaced by the optimised Timing Chain Kit (part no. 559 0156 30). This kit contains the wider chain with the corresponding chain sprockets for the crankshaft and camshaft. The new kit (Figure 1) can be used to repair engines with both the narrow and wide versions of the chain.

Important

To ensure the permanent operational safety of the timing drive, all of the parts in the Timing Chain Kit must be used. This is especially important for engines with the narrow chain design (up to model year 2011), as the wider chain does not fit on the old chain wheels on these engines.

Professional replacement of the crankshaft chain sprocket does not require any special tools. Use of the INA installation tool kit, item no.: 400 0588 10 (Figure 2), is recommended.



Figure 2: INA installation tool kit for replacing the crankshaft chain sprocket

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264
 Fax: +44 (0) 1432 375 760
 aftermarket.uk@schaeffler.com
 www.repxpert.co.uk

Issued 05.2021 INA 0197 Technical content subject to change
 OE Manufacturer's names and numbers are used for reference purposes only
 © 2021 Schaeffler Automotive Aftermarket GmbH & Co. KG