



54376 = 52594

- Ⓔ Please note: these pumps are interchangeable.
- Ⓓ Bitte beachten: diese beiden Pumpen sind austauschbar!
- Ⓓ Vă rugăm să rețineți: aceste două pompe sunt interschimbabile!
- Ⓓ Bemærk: Begge disse pumper kan udskiftes!
- Ⓕ Huomaa: nämä pumput ovat keskenään vaihdettavia.



GKN Driveline Service GmbH Nussbaumweg 19-21 | 51503 Roesrath | Germany
www.gknautomotive.com | © GKN Automotive. All rights reserved.

Disclaimer of Liability

The information contained on this leaflet ("Service") is for general information purposes only. The application of any GKN Automotive product subject to the Service must be performed by certified professionals. GKN Automotive assumes no responsibility for errors or omissions in the contents on the Service. In no event shall GKN Automotive be liable for any special, direct, indirect, consequential, or incidental damages or any damages whatsoever, whether in an action of contract, negligence or other tort, arising out of or in connection with the use of the Service or the contents of the Service. GKN Automotive reserves the right to make additions, deletions, or modification to the contents on the Service at any time without prior notice.