



## LuK Service Info



# Part Nr: 631 0261 09/10/11 — 310/310mm ZGW6


Manufacturer: NEW HOLLAND - FIAT

Info: Flywheel Information/  
Schwungradinformation/  
Informations de volant-moteur/  
Información del Volante-motor/  
Informazioni volano


Art.-Nr.: 631 0261 09/10/11





631 0261 09 = 231 0032 10 + 331 0103 10  
631 0261 10 = 231 0032 10 + 331 0103 10 + 500 0786 30  
631 0261 11 = 231 0032 10 + 331 0103 10 + 500 0059 10 + 410 0026 00


 The location recess of 0.5mm depth and external register diameter of 362.114 – 362.290mm must be restored when flywheel is machined.

guide de 362.114 – 362.290 mm lorsque le volant-moteur est rectifié.

 Bei der Bearbeitung des Schwungrads müssen die Einbautiefe von 0,5 mm und der externe Registerdurchmesser von 362.114–362.290 mm wiederhergestellt werden.

 Deben mantenerse la distancia relativa a la zona de fricción a 0,5 mm de profundidad y el diámetro de fricción externo a 362.114 – 362.290 mm cuando el volante esta mecanizado.

 Il faut restaurer l'épaule de montage de 0,5 mm de profondeur et le diamètre de l'épaulement

 Riportare la cavità della sede ad una profondità di 0,5 mm e il diametro di centraggio esterno a 362.114 – 362.290 mm quando si rettifica il volano.



631 0261 09

- For accurate model information please see LuK catalogue
- Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog
- Pour plus d'information sur les applications veuillez vous référer au catalogue LuK
- Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK
- Per informazioni sul modello consultare il catalogo LuK

**You want more? We can help!**

Phone: +44 (0) 1432 264 264  
Fax: +44 (0) 1432 375 760  
aftermarket.uk@schaeffler.com  
www.repexpert.co.uk

SCHAEFFLER  
**REP>XPERT**