

SERVICE INFO



Assembly instructions for axle nut 434 0431 10

Vehicle manufacturer: MAN

Models:

Commercial

vehicles: E Series, F 2000, M 2000 L, M 2000 M, TGA, TGM, TGS, TGX

Coaches: 18 ..., Lion's Coach, Lion's Star, NG, NL, NM, NÜ, RH, SG, SL, SÜ, Tourliner, ÜL

OE number: 81.90620-0086

Part No.: 434 0431 10 (axle nut)
801974AE.H195 (TAM)



Image 1: The axle nut (434 0431 10) is available as an FAG accessory.

If the axle nut becomes loose when working on the steering swivel, when replacing the TAM (Truck Axle Module) 801974AE.H195 for instance, the axle nut will need to be replaced. This nut is a self-locking nut and may only be used once.

For this reason, Schaeffler Automotive Aftermarket is offering the axle nut (part number 434 0431 10) as part of its accessories with immediate effect.

Tightening torque: 740 Nm



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 05.2011

FAG 0019

Subject to technical changes
© 2011 Schaeffler Automotive Aftermarket

Any reference to replacement part numbers for vehicle manufacturers is for comparison purposes only.

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100